

Renantis UK Limited

The Repowered and Extended Ben Aketil Wind Farm

Environmental Impact Assessment Report – Figures (Volume 2a)

663617







RSK GENERAL NOTES

Project No.:	G/P/663617/09/04/03/03/04/Vol_2a Rev04
Title:	Environmental Impact Assessment Report – Figures (Volume 2a)
Client:	Renantis UK Limited (formerly Falck Renewables Wind Limited)
Date:	May 2023
Office:	Glasgow
Status:	Final

RSK Environment Ltd (RSK) has prepared this report for the sole use of the client, showing reasonable skill and care, for the intended purposes as stated in the agreement under which this work was completed. The report may not be relied upon by any other party without the express agreement of the client and RSK. No other warranty, expressed or implied, is made as to the professional advice included in this report.

Where any data supplied by the client or from other sources have been used, it has been assumed that the information is correct. No responsibility can be accepted by RSK for inaccuracies in the data supplied by any other party. The conclusions and recommendations in this report are based on the assumption that all relevant information has been supplied by those bodies from whom it was requested.

No part of this report may be copied or duplicated without the express permission of RSK and the party for whom it was prepared.

Where field investigations have been carried out, these have been restricted to a level of detail required to achieve the stated objectives of the work.

This work has been undertaken in accordance with the quality management system of RSK Environment Ltd.



Table of Contents

Figure 2.1: Site Location Figure 2.2: Design Iterations A-D
Figure 2.2: Design Iterations E-H
Figure 2.3: Site Layout
Figure 2.4: Indicative Wind Turbines
Figure 2.5: Indicative Wind Turbine Foundations
Figure 2.6: Indicative Crane Hardstanding
Figure 2.7: Indicative Track Details
Figure 2.8: Indicative Cable Trench Details
Figure 2.9: Indicative Construction & Substation Compounds Plans
Figure 2.10: Indicative 20MW Battery Storage Layout
Figure 2.11: Indicative Substation Building Elevations
Figure 6.1: Landscape Context
Figure 6.2: Cumulative Search Area
Figure 6.3: Landscape Character and Cumulative Sites
Figure 6.4: Topography
Figure 6.5: Bare Ground ZTV to Tip and Hub
Figure 6.6: Screening ZTV to Tip and Hub
Figure 6.7: Recreational Routes Screening ZTV to Tip and Hub
Figure 6.8: Night Time ZTV - Nacelle Lights
Figure 6.9: Cumulative ZTV - Ben Aketil with Edinbane
Figure 6.10: Cumulative ZTV - Ben Aketil with Ben Sca
Figure 6.11: Cumulative TV - Ben Aketil with Glen Ullinish
Figure 6.12: Cumulative ZTV - Ben Aketil with Beinn Mheadhonach (Consented)
Figure 6.13: Cumulative ZTV - Ben Aketil with Beinn Mheadhonach (Scoping)
Figure 6.14: Cumulative ZTV - Ben Aketil with Balmeanach
Figure 7.1: Statutory Sites Designated for Ecological Interest
Figure 7.2a: Phase 1 Habitat Survey (North)
Figure 7.2b: Phase 1 Habitat Survey (South)
Figure 7.3a: National Vegetation Classification Survey (North)
Figure 7.3b: National Vegetation Classification Survey (South)
Figure 7.4: Terrestrial Mammal Survey
Figure 7.5: Bat Roost Survey
Figure 7.6: Bat Activity Survey
Figure 7.7: Fish Habitat Survey
Figure 8.1: Statutory Designated Sites for Ornithological Interest
Figure 8.3a: Vantage Point (VP) Survey Plan (VP1, VP2, VP3 and VP7)
Figure 8.3b: Vantage Point (VP) Survey Plan (VPA and B)
Figure 8.4: Breeding Bird Survey Areas 2021 and 2022
Figure 8.5a: Target Species Flight Activity March 2021 to April 2022 (golden eagle)
Figure 8.5b: Target Species Flight Activity March 2021 to April 2022 (white-tailed eagle)
Figure 8.5c: Target Species Flight Activity March 2021 to April 2022 (other raptors)
Figure 8.5d: Target Species Flight Activity March 2021 to April 2022 (all other target species)
Figure 8.6: Moorland Breeding Bird Survey Results (2021 and 2022)
Renantis UK Ltd



Figure 9.1a: Bedrock Geology Figure 9.1b: Superficial Geology Figure 9.2: Carbon and Peatland Classes Figure 9.3: Peat Depth Figure 9.4: Hydrological Catchments Figure 9.5: Private Water Supplies Figure 9.6: Water Quality Monitoring Figure 10.1: Cultural Heritage - Inner Study Area Figure 10.2: Cultural Heritage - Outer Study Area Figure 10.3: Cultural Heritage - Cumulative Developments and Visualisation Locations Figure 10.4: Barpannan, Two Chambered Cairns, Vatten Durnish (SM 893) - Visualisations 10.4a-f Figure 10.5: Dun Flashader, Broch, Skye (SM 911) - Visualisations 10.5a-b Figure 10.6: Ullinish, Fort, Bracadale (SM 930 - Visualisations 10.6a-f Figure 10.7: Dun Osdale, Broch 850 m N of Osdale (SM 3493) - Visualisations 10.7a-f Figure 10.8: Dun Feorlig, broch 230 m NNE of Feorlig Farm (SM 3494) - Visualisations 10.8a-b Figure 10.9: Ardmore, Chapel and Burial Ground 230 m SW of (SM 3884) - Visualisations 10.9a-f Figure 10.10: Dun Neil, Dun 420 m SW of Ardmore (SM 3885) - Visualisations 10.10a-b Figure 10.11: St Mary's Church and Burial Ground, Dunvegan (SM 9249) - Visualisations 10.11a-c Figure 10.12: Dun Arkaig, Broch (SM 13662) - Visualisations 10.12a-c Figure 10.13: Abhainn Bhaile Mheadhonaich, broch and standing stone 145m SE of An Cairidh (SM 13664) - Visualisations 10.13a-c Figure 10.14: Seascape view Loch Bracadale - Visualisations 10.14a-b Figure 11.1: Traffic Study Area Figure 11.2: Traffic Count Points Figure 11.3: Traffic Accident Data (2017-2021) Figure 11.4: Indicative Northern Access Junction Modifications Figure 11.5: Indicative Southern Access Junction Modifications Figure 12.1: Predicted operational noise levels for maximum sound power level Ben Aketil existing Figure 12.2: Predicted operational noise levels for maximum sound power level - Ben Aketil repowering and extension Figure 12.3: Predicted operational noise levels for maximum sound power level - Ben Aketil existing and extension

Figure 13.1: Socio-economic features

Figure 16.1: Telecommunications Links

Figure 16.2: Shadow Flicker Assessment Study Area